

Optional Accessories

- **07GZA000**: Scriber
 - **953638**: Holding bar for test indicator (length: 50 mm)
 - **900209**: Holding bar for test indicator (length: 100 mm)
 - **953639**: Holding bar for test indicator (length: 2 in)
 - **900306**: Holding bar for test indicator (length: 4 in)
 - **900321**: Swivel clamp used with holding bar (metric)
 - **900322**: Swivel clamp used with holding bar (inch)
 - **902053**: Clamp (with dovetail groove, $\varnothing 6$ and $\varnothing 8$ holes)
- Note: A test indicator can be mounted on a height gage using a holding bar and clamp.

Dial Height Gage SERIES 192 — With digital counter

- Easy and error-free reading with both up and down digital counters as well as a dial.

- Fits comfortably in the hand and moves easily on the surface plate.



- Can be zero-set at any arbitrary position.
- Provided with a large adjustment wheel for easy height adjustment.
- Clamp can be operated easily and securely.



192-130

- Carbide tipped scriber (**07GZA000**) is attached as standard. (Standard accessory: Scriber clamp **05GZA033**)
- For precision Black Granite Surface Plates, refer to page E-46.

Note: Do not hold the height gage by the column as this can affect the accuracy.

SPECIFICATIONS

Metric					
Order No.	Range (mm)	Accuracy (mm)	Graduation (mm)	Height (mm)	Mass (kg)
192-130	0 - 300	± 0.03	0.01	470	4.2
192-131	0 - 450	± 0.05		648	9.2
192-132	0 - 600			798	9.8
192-133	0 - 1000	± 0.07		1220	17.0

Inch					
Order No.	Range (in)	Accuracy (in)	Graduation (in)	Height (mm)	Mass (kg)
192-150	0 - 12	± 0.0015	0.001	470	4.2
192-151	0 - 18	± 0.002		648	9.2
192-152	0 - 24			798	9.8
192-153	0 - 40	± 0.003		1220	17.0

DIMENSIONS

