
For High Speeds MEGA NEW BABY CHUCK PAT.

High speed version of NEW BABY CHUCK boasting a history of results. Makes high speed machining possible in addition to its high accuracy and versatility.



BBT30

DUAL CONTACT

BBT/BT

BIG-PLUS (BBT Shank) tools can be used on both BIG-PLUS spindles and conventional **BT spindles**.

| DDIJU | | Did | I LOO (DD I | Orianny to | ols call be asea of t | Sour Brail Ede Spirial | co and conventional | Di Spiridics. |
|-----------------------------|-------------------------|-----|-------------|----------------|-----------------------|------------------------|---------------------|---------------|
| BIG-PLUS BBT SHANK Model | Clamping diameter ød | øD | L | L ₁ | Н | Collet Model | Nut Model | Weight (kg) |
| BBT30-MEGA 6N- 60 | 0.25 - 6 | 20 | 60 | 32 | 23 - 43 | NBC 6-□ | MGN 6 | 0.47 |
| - 75 | | | 75 | 47 | | | | 0.50 |
| - 90 | | | 90 | 62 | | | | 0.53 |
| -105 | | | 105 | 77 | | | | 0.56 |
| -120 | | | 120 | 90 | | | | 0.59 |
| -MEGA 8N- 60 | 0.5 - 8 | 25 | 60 | 34 | 26 - 45 | NBC 8-□ | MGN 8 | 0.51 |
| - 75 | | | 75 | 49 | | | | 0.56 |
| - 90 | | | 90 | 64 | | | | 0.61 |
| -105 | | | 105 | 79 | | | | 0.67 |
| -120 | | | 120 | 92 | | | | 0.72 |
| -MEGA10N- 60 | 1.5 - 10 | 30 | 60 | 34 | 38 - 48 | NBC10-□ | MGN10 | 0.54 |
| - 75 | | | 75 | 49 | | | | 0.61 |
| - 90 | | | 90 | 64 | | | | 0.68 |
| -105 | | | 105 | 79 | | | | 0.75 |
| -120 | | | 120 | 94 | | | | 0.82 |
| -MEGA13N- 60 | 2.5 - 13 | 35 | 60 | 34 | 44 - 63 | NBC13-□ | MGN13 | 0.57 |
| - 75 | | | 75 | 49 | | | | 0.67 |
| - 90 | | | 90 | 64 | | | | 0.77 |
| -105 | | | 105 | 79 | | | | 0.87 |
| -120 | | | 120 | 94 | | | | 0.97 |
| -MEGA16N- 60 | 2.5 - 16 | 42 | 60 | 37 | 48 - 63 | NBC16-□ | MGN16 | 0.61 |
| - 75 | | | 75 | 52 | 48 - 68 | | | 0.75 |
| - 90 | | | 90 | 67 | | | | 0.89 |
| -105 | | | 105 | 82 | | | | 1.04 |
| -MEGA20N- 60 * | 2.5 - 20 | 46 | 60 | _ | 70 | NBC20-□ | MGN20 | 0.64 |
| - 75 | | | 75 | _ | 51 - 68 | | | 0.78 |
| - 90 | | | 90 | _ | | | | 0.93 |
| -105 | | | 105 | _ | | | | 1.08 |
| -MEGA25N- 85 ** | 15.5 - 25.4 | 60 | 85 | _ | 80 | NBC25-□ | MGN25 | 1.13 |

^{1.} Nut is included. Collet, wrench, and adjusting screw must be ordered separately.

- 2. Weight includes the nut but not the collet.
- 3. Center through coolant supply is available.
- 4. Please note that the practical spindle speed may be considerably influenced by the machine rigidity and tool balance. When using, slowly ramp up to the appropriate speed starting from slow speeds.
- 5. Tool adjustment amount "H" indicates the adjustment length with an Adjusting Screw.
- * marked models cannot be used with Adjusting Screws.
- H dimension is the max. tool shank length that can be inserted into the

When ordering a MEGA PERFECT SEAL, the "Nut-Less Body" without the standard nut attached is also available.



